

Neighborhood Walk Follow Up Report

Mt. Airy

8/10/2005

ID	DATE	LOCATION	PROBLEM	ASSIGNED TO (DEPT)	DEPT CONTACT	STATUS
50	8/10/2005	Behind Kirby business district	Metal guard rail piece laying in middle of lot	Health		Civil Citation issued to property owner.
51	8/10/2005	5552 Colerain (Pro Image Barber Shop)	Bullet holes in glass	B&I		orders complied
52	8/10/2005	5542 Colerain (Winner's Phase II Salon)	Glass shot out	B&I		orders issued: repair windows - pph to be set
53	8/10/2005	5544 Colerain (Pony Keg)	B&I issues. Romex exposed on exterior light. Stand alone telephone out of order.	B&I		repair orders issued: electric - pph to be set
54	8/10/2005	Small lot between 5530 Colerain and Klosterman Dry Cleaners	Litter, debris	Health		Lot to be cleaned by 8/29/04 per Mr. Klosterman, owner.
55	8/10/2005	5526 Colerain	Cracked front window	B&I		orders complied
56	8/10/2005	Bus stop in front of Warsaw wireless on corner of North Bend and Colerain	Bus stop needs to be cleaned up. Litter, etc.	Health		Area was clean at the time of inspection on 8/16/05.
57	8/10/2005	5551 1/2 Colerain (Kids Lil' Foot)	Extension cord running across parking lot. Stand alone sign in parking lot	Fire; B&I		Fire addressed this issue with the owner, who removed the cord. Fire also provided the owner withsome information on how to accomplish his objective wihout violating the Fire Code.